



WOHNUNG 1

83,3 qm


23.07.2009






WOHNUNG 2

82,1 qm



23.07.2009





WOHNUNG 3

82,7 qm




23.07.2009






WOHNUNG 4 137,9 qm




23.07.2009




WOHNUNG 5

132,4 qm




23.07.2009




WOHNUNG 6

99,4 qm

23.07.2009







WOHNUNG 7

96,6 qm


23.07.2009






WOHNUNG 8

138,0 qm





23.07.2009



WOHNUNG 9 132,8 qm


23.07.2009






WOHNUNG 10

99,3 qm




23.07.2009




WOHNUNG 11

96,7 qm





23.07.2009



WOHNUNG 12 136,3 qm


23.07.2009






WOHNUNG 13 132,8 qm


23.07.2009






WOHNUNG 14

99,6 qm




23.07.2009




WOHNUNG 15


97,1 qm




23.07.2009



WOHNUNG 16 137,3 qm




23.07.2009




WOHNUNG 17

85,4 qm





23.07.2009



WOHNUNG 18 71,3 qm


23.07.2009






WOHNUNG 19 71,1 qm


23.07.2009







WOHNUNG 20

93,1 qm




23.07.2009





WOHNUNG 21

78,5 qm




23.07.2009





WOHNUNG 22

59,9 qm




23.07.2009






WOHNUNG 23

73,7 qm

23.07.2009







WOHNUNG 24

50,0 qm


23.07.2009





WOHNUNG 25


45,5 qm

23.07.2009







WOHNUNG 26




65,2 qm

23.07.2009





WOHNUNG 27

80,7 qm




23.07.2009





WOHNUNG 28

60,3 qm





23.07.2009



WOHNUNG 29


74,2 qm

23.07.2009






WOHNUNG 30

69,9 qm





23.07.2009



WOHNUNG 31

35,3 qm


23.07.2009





WOHNUNG 32

65,7 qm

23.07.2009









WOHNUNG 33

81,0 qm

23.07.2009







WOHNUNG 34


61,0 qm

23.07.2009





WOHNUNG 35

73,5 qm




23.07.2009






WOHNUNG 36

70,6 qm

23.07.2009








WOHNUNG 37

35,4 qm



23.07.2009



WOHNUNG 38

65,8 qm


23.07.2009





WOHNUNG 39

81,3 qm

23.07.2009








WOHNUNG 40

60,9 qm

23.07.2009








WOHNUNG 41

73,4 qm

23.07.2009









WOHNUNG 42

70,7 qm

23.07.2009







WOHNUNG 43

35,4 qm


23.07.2009





WOHNUNG 44

65,8 qm

23.07.2009









WOHNUNG 45

74,3 qm

23.07.2009







WOHNUNG 46

60,0 qm


23.07.2009





WOHNUNG 47

68,3 qm


23.07.2009








WOHNUNG 48

65,7 qm





23.07.2009



WOHNUNG 49

34,0 qm

23.07.2009



WOHNUNG 50

65,9 qm

23.07.2009